



(On I-80, Exit 267 South) 2096 Moscow Road, Moscow, Iowa 52760

Phone: (800)321-3494 or (563)724-3396 Fax: (563)724-3408 Internet: www.hwhcorp.com

PRODUCT/SERVICE BULLETIN

ISSUE DATE: March 8, 1993

TO: All O.E.M Manufacturers and Installers

FROM: HWH CORPORATION

RE: Repairing or Installing an AP8525 Leveling Jack

REPAIRING OR INSTALLING AN AP8525 LEVELING JACK

Anytime an AP8525 jack (16,000# for a 610 System) is installed or repaired, the following procedure must be followed:

1. Turn the system on and bring the jacks to the vertical position.
2. Extend and retract the jacks in the manual mode three to four times before lifting the coach.

NOTE: Items 1 and 2 must be followed to purge air from the jacks and the hydraulic lines. If this procedure is not followed, damage may result to the actuator.

Please contact HWH CORPORATION at (800) 321-3494 for technical advice or assistance.

**MI95.40
30MAR01**