

MECHANISM AP19951 AP19952	DUAL CYLINDER ROOM EXTENSION – 21.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP19950 KIT SEE > MR41.2005.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90458 (21.5” STROKE) REPLACES AP15324 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90470 (8.450” STROKE) REPLACES AP14101 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP20515	SINGLE CYLINDER ROOM EXTENSION – 21.0” STROKE – AP20514 KIT SEE > MR41.1100.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90688 (27.0” STROKE) REPLACES AP15818 HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)
MECHANISM AP24032 AP24033	LATERAL ARM (WARDROBE) ROOM EXTENSION – 14.5” STROKE (WITH SYNC. CYLINDER) AP23998 KIT SEE > MR41.2800.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90901 (11.39” STROKE) REPLACES AP23672 SYNCHRONIZING CYLINDER_____ ITEM 4 - RAP90904 (1.57” STROKE) REPLACES AP23696 HOSE ASSEMBLIES_____ ITEM 2 - RAP24636 (ROD END) RAP25086 (CAP END)
MECHANISM AP24252	SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP24251 KIT SEE > MR41.1100.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91021 (27.0” STROKE) REPLACES AP28682 HOSE ASSEMBLIES_____ ITEM 3 - RAP24639 (AP24639) ITEM 4 - RAP24635 (AP24635)
MECHANISM AP26584 AP26585	DUAL CYLINDER LEVEL OUT ROOM EXTENSION – 31.0” STROKE (WITH SYNC. CYLINDER) AP26583 KIT SEE > MR41.2200.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91199 (32.0” STROKE) REPLACES AP24262 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90442 (12.570” STROKE) REPLACES AP16484 TUBE KIT_____ ITEM 2 - RAP91024 - REPLACES AP26587
MECHANISM AP31677 AP31678	UNIVERSAL FLAT OUT – 25.0” STROKE (WITH SYNCHRONIZING CYLINDER) – AP31676 KIT SEE > MR41.2687.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91760 (36.0” STROKE) REPLACES AP31645 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90440 (10.095” STROKE) REPLACES AP16509 TUBE KIT_____ ITEM 2 - RAP92080 - REPLACES AP31651 HOSE ASSEMBLIES_____ ITEM 4 - RAP24653 (AP24653) ITEM 5 - RAP24648 (AP24648) LIFT MECHANISMS_____ ITEM 10 - RAP91746 (AP32555) ITEM 11 - RAP91748 (AP32556)
MECHANISM AP33348 AP33349	LATERAL ARM ROOM EXTENSION – 16.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP33347 KIT SEE > MR41.2825.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91203 (6.150” STROKE) REPLACES AP26255 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP91013 (1.810” STROKE) REPLACES AP28566 TUBE KIT_____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES_____ ITEM 4 - RAP23738 (AP23738) ITEM 5 - RAP23738 (AP23738)

MECHANISM AP34218 AP34219	UNIVERSAL LEVEL OUT ROOM EXTENSION – 25.0” STROKE (WITH SYNC. CYLINDER) AP34217 KIT SEE > MR41.2683.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91702 (34.0” STROKE) REPLACES AP31461 LIFT CYLINDER ASSEMBLY_____ ITEM 10 - RAP91992 (2.75” LIFT) REPLACES AP34390 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90440 (10.095” STROKE) REPLACES AP16509 LIFT SYNCHRONIZING CYLINDER_ ITEM 11 - RAP92316 - REPLACES AP38264 TUBE KIT_____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES_____ ITEM 4 - RAP24638 (AP24638) ITEM 5 - RAP24632 (AP24632)
MECHANISM AP35776	CYLINDER ASSEMBLY – 60.0” STROKE – AP35775 KIT CYLINDER ASSEMBLY_____ RAP92037 (60.0” STROKE) - REPLACES AP35776
MECHANISM AP36890	CYLINDER ASSEMBLY – 30.0” STROKE – AP36889 KIT CYLINDER ASSEMBLY_____ RAP92372 (30.0” STROKE) - REPLACES AP36890
MECHANISM AP38383 AP38384	UNIVERSAL LEVEL OUT – 26.0” STROKE (WITH SYNC. CYLINDER) AP38677 AND AP42484 KITS SEE > MR41.2690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 14 - REPLACES AP38604(2.75” LIFT) RAP92260 SHORT W/90deg.fitting SYNCHRONIZING CYLINDER_____ RAP92260-01 LONG W/90deg.fitting RAP92260-02 45 deg. fitting LIFT SYNCHRONIZING CYLINDER_ ITEM 3 - RAP92469 (9.130” STROKE) REPLACES AP39275 TUBE KIT_____ ITEM 15 - RAP92316 - REPLACES AP38264 HOSE ASSEMBLIES_____ ITEM 2 - RAP92079 - REPLACES AP38267 ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP41562 AP41563	DUAL CYLINDER ROOM EXTENSION – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP41601 KIT SEE > MR41.2005.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90629 (30.5” STROKE) REPLACES AP17365 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252